



Burlington, WA	Corporate Laboratory (a)	1620 S Walnut St	Burlington, WA 98233	800.755.9295 • 360.757.1400
Bellingham, WA	Microbiology (b)	806 Orchard Dr Ste 4	Bellingham, WA 98225	360.715.1212
Portland, OR	Microbiology/Chemistry (c)	9150 SW Pioneer Ct Ste W	Wilsonville, OR 97070	503.682.7802
Corvallis, OR	Microbiology (d)	540 SW Third Street	Corvallis, OR 97333	541.753.4946



FL NELAP E871040

INORGANIC COMPOUNDS (IOC) REPORT


Client Name: Hat Island Community
3616 Colby Ave #335
Everett, WA 98201

Reference Number: 18-27216
Project: Arsenic

Date Collected: 7/23/18 11:00
System ID Number: **31593N**
Lab Number: **046-55291**
Sample Location: G-Tank Pump House (Pre Distribution)
Sample Purpose: C - Compliance
Sample Composition: Single Source

Approved by: anp

Authorized by:


Lawrence J Henderson, PhD

Director of Laboratories, Vice President

Field ID: Arsenic
System Group Type: A
System Name: HAT ISLAND COMMUNITY INC
County: Snohomish
Source Number: **07**
Multiple Sources:
Date Received: 7/24/18
Report Date: 8/6/18
Sample Type: B - Before treatment
Sampled By: Chris Inman
Sampler Phone: 2082836443

DOH#	ANALYTES	RESULTS	UNITS	SRL	Trigger	MCL	Analyst	METHOD	Lab	Analyzed	COMMENT
4	EPA Regulated ARSENIC	0.004	mg/L	0.001		0.010	bj	200.8	a	08/02/18	

NOTES:

SRL (State Reporting Level): indicates the minimum reporting level required by the Washington Department of Health (DOH).

MCL (Maximum Contaminant Level) maximum permissible level of a contaminant in water established by EPA; Federal Action Levels are 0.015 mg/L for Lead and 1.3 mg/L for Copper. Sodium has a recommended limit of 20 mg/L. A blank MCL value indicates a level is not currently established.

Trigger Level: DOH Drinking Water Response level. Systems with compounds detected in excess of this level are required to take additional samples. Contact your regional DOH office.

ND (Not Detected): indicates that the parameter was not detected above the Specified Reporting Limit (SRL).

An * in front of the parameter name indicates it is not NELAP accredited but it is accredited through WSDOH or USEPA Region 10.

These test results meet all the requirements of NELAC, unless otherwise stated in writing, and relate only to these samples.

If you have any questions concerning this report contact Lawrence J Henderson, PhD, Director of Laboratories, Vice President, at the toll-free phone number above.